

CAT# MSP-4

Motor Speed Control

Preliminary connection diagram for PWM speed control. The 8-pin connector is a throttle control. Connect 1k pot to pins 2 and 4 (purple and grey).

