

CAT# PS-350

Hook-up Sheet

Note: There must be a load of at least 250 ma on the 5 volt output (V1) for the supply to function properly

V1 = 5V @ 25A

V2 = 12V @ 10A

V3 = 12V @ 6A

**AC
Input**



+V1
+V1
-V1
-V1
+V2
-V2
+V3
-V3

**DC
Outputs**