

202 WATT POWER SUPPLY

CAT# PS-4160

This power supply requires a jumper or on-off switch between the Green and Blue wires on the P-1 Connector. Unlike many switching supplies, it does not require a load to function. Once the connection is made it will turn on.

