


SELF-FUSING RUBBER TAPE


CAT# SFT-5



To use, remove 2" to 3" of tape from the roll, remove the liner...



stretch tape to twice the supplied width and...



wrap it spirally around the object with a 50% overlap. In minutes the tape will react with itself to provide protection from moisture, most chemicals, and provide insulation to 490V per mil. Since the tape does not use mastic or adhesive it can be removed easily without leaving any residue.